From: <u>Brass, Agaha</u>

To: <a href="mailto:louis.martin@la.gov">louis.martin@la.gov</a>; <a href="mailto:sherri.courtney@la.gov">sherri.courtney@la.gov</a>; <a href=

regenia.taylor@la.gov; regenia.taylor@la.gov; karen.price2@la.gov; karen.price2@la.gov; Greg

Fife/R6/USEPA/US@EPA; Sherman, Robert; Bordelon, David

Cc: <u>Hadwin, Erik;</u> <u>Howard, Larry</u>

Subject: FW: Bayou Corne Natural Gas Seep-Activities conducted on Saturday, August 25, 2012 between 0730 hrs to

2000 hrs

**Date:** 08/25/2012 07:22 PM

Activities Performed by EPA START personnel on Saturday, August 25, 2012 between 0730 hrs to 2000 hrs:

• 24/7 air monitoring/oversight was conducted at the drilling site. Duties included:

- 1. Review of facility's real-time monitoring data with the facility/contractor personnel (Sage/Code Red)
  - i. One elevated VOC count (19.8) was noticed at Unit 1 but personnel attributed it to boat traffic as the reading went back to 0.0 within an hour.
- 2. Review of alarm readings and also calibration and maintenance records for facility's air monitoring instruments
- 3. Hand-held monitoring at 9 monitoring points.
  - i. Parameters monitored included CO, H<sub>2</sub>S, VOCs, LEL, and O<sub>2</sub>. All readings were below the low action levels and within normal O<sub>2</sub> readings.
  - ii. Monitoring was conducted using the MultiRae. Between 1900 hrs and 2000 hrs on August 25, 2012, no monitoring at the 9 monitoring points was being conducted as the next scheduled monitoring run was to be 2000 hrs. Although, a ight rain began and may be a limiting factor for the 2000 hrs monitoring run. Between 0800 hrs to 2000 hrs on August 25, 2012, EPA START completed 6 rounds of hand-held monitoring at the 9 monitoring points.
- On the 5<sup>th</sup> run START-3 contractors noticed the AreaRaes at LDEQ points 3 and 9 were frequently fluctuating between 0.0 and 0.4 on the VOC meters but were 0.0 on the MultiRae during the same monitoring periods. During the 5<sup>th</sup> monitoring run facility/contractor personnel were installing a pipeline and ditch at the entrance to point 6. On the 6<sup>th</sup> run they move closer to the drilling rig and were installing a pipeline and ditch there. No elevated reading were noticed on the MultiRae during either installation. Lots of heavy equipment traffic (18-wheelers carrying backhoes, cherry pickers, and bulldozers) existed on the site throughout the day but no elevated readings were noticed on the MultiRae. No additional problems or issues were encountered.

## Agaha Y. Brass

Senior Project Scientist



13702 Coursey Blvd., Bldg #7, STE A

Baton Rouge, LA 70817 Office: 225-297-5404

Mobile: 225-335-3119 Fax: 225-293-8339

CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary



information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return email and delete this email from your system. Thank you.

This Email message contained an attachment named image001.jpg

which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at  $(866)\ 411-4$ EPA (4372). The TDD number is  $(866)\ 489-4900$ .

\* ATTACHMENT NOT DELIVERED \*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*